























TORX® TORX all sizes in list

ABOUT SPEC. BITS				TORX		TORX Screwdrivers							TORX Precision bits and sockets				
				Size	Tip diameter												
Hexagon socket set screws	Socket head screws	Tapping screws	Machine screws	TORX Size	 mm	No. 5400TX	No. TX-10	No. TX-11	No. 8500TX	No. 8500TX	No. Q4T	No. Q6T	No. D71	No. D73	No. D76	No. NT	
																	
1.6 1.8		(1)	(1)	T1	0.84								●	●			
2		(1.2)	(1.2)	T2	0.94								●	●			
2.2		(1.4)	(1.4)	T3	1.12								●	●			
		(1.6) (1.7)	(1.6) (1.7)	T4	1.3								●	●			
2.5				T5	1.37	●			●				●	●	●		
3		2	2	T6	1.65	●			●				●	●	●	●	
3.5				T7	1.97		●		●				●	●	●		
4	2.5	2.5	2.5	T8	2.3		●		●				●	●	●	●	
4.5				T9	2.48		●		●				●	●	●		
5	3	3	3	T10	2.72		●	●	●	●	●		●	●	●	●	
	3.5	3.5	3.5	T15	3.26		●	●	●	●	●				●	●	
6		4 4.5	4	T20	3.84		●	●	●	●	●				●	●	
7	4	5	5	T25	4.4		●	●	●	●	●				●	●	
8	4.5 5			T27	4.96		●	●	●	●	●				●		
	6	6	6	T30	5.49		●	●	●	●	●	●					
10	7	8	8	T40	6.6		●	●	●	●		●					
12	8			T45	7.77							●					
14	10	10	10	T50	8.79							●					
				Page		5	5	5	5	6	6	7	7	8	8	8	9



 Type

